X-SERIES



Process table

Electrode























Gouging











optionally available

Operation concepts





BasicPlus

- "3 steps to weld" operating concept
- 7 segment display, exact to the amp
- Electrode pre-selection for optimum results
- HotStart on/off (can be set in submenu)
- Can switch to TIG function
- acan be used with semi-automatic MIG-MAG wire feed cases by means of CV curve

ControlPro

- "3 steps to weld" operating concept
- 7-segment display, exact to the amp
- Advance selection of electrode for optimum results
- Hotstart on/off (can be set in submenu)
- Can switch to TIG function
- can also be used with semi-automatic MIG-MAG wire feeders
- with special vertical seam welding function
- as PST variant, also with polarity reversal function



TECHNICAL DATA



Ausführungen



